

JOTAPLAST 07

Solvent-free, PVA emulsion paint



GF10105/GF10106 04/2008

Jotaplast 07 is a water-borne, 100 % solvent free emulsion paint for indoor use. It is used as an intermediate coat and as a topcoat on plaster, concrete, fillers, building boards, glass fibre fabrics, etc.

PHYSICAL DATA:

Type.....	PVA copolymer emulsion paint.
Colour.....	White, A-, B- and C-base for tinting on Jotun Multicolor tinting system
Gloss.....	07 silk matt
Viscosity.....	180 cP, 110 K.U.
Specific gravity.....	Approx. 1,30
Solids by volume %.....	39

RECOMMENDATION FOR USE:

Film thickness, dry.....	35 - 55 micrometres
Film thickness, wet.....	80 - 130 micrometres
Recommended spreading rate.....	7 - 10 m ² /litre
Application methods.....	Roller, brush or airless spray

Guiding data for airless spray:

Nozzle.....	0,021"
Spray angle.....	65 - 80 degrees
Pressure at nozzle.....	Minimum 150 kg/cm ²

Drying times, (guiding data at 23 deg. C, 50% R.H.):

Dust dry.....	Approx. 1 hour
Interval between coats.....	Approx. 2 hours
Dry to use.....	Approx. 24 hours
	Deviations at changes in temperature, air humidity, ventilation and film thickness.
Thinner/cleaning agent.....	Water / Soap and water

SAFETY DATA:

A Material Safety Data Sheet has been issued for this product.
EU limit value for this product (cat. A/a): 30 g/l (2010). This product contains max 1 g/l VOC.

FLAMMABILITY CLASSIFICATION:

Norway..... -

MISCELLANEOUS:

Tinting.....	Add maximum 10 % of Jotun Tinting Colours
Size of containers.....	3 and 10 litres. Bases 2,7 and 9 litres.
Remarks.....	Temperature of substrate and air must be minimum + 10° C

during application. Frostfree freight and storage. Contents of tins with different batch numbers must be mixed before use, to avoid possible colour deviations. Bases must not be used untinted.

DIRECTIONS FOR USE:

PRETREATMENT

The substrate must be clean and dry. Old glossy paint to be sanded, and if necessary washed with a suitable detergent prior to priming with Jotanol. Bare iron and nail heads must be primed with an anticorrosive.

DIRECTIONS FOR USE

Jotaplast 07 should be applied richly and evenly.

The above information is given to the best of our knowledge based on laboratory tests and practical experience. However, as the product is often used under conditions beyond our control, we cannot guarantee anything but the quality of the product itself. We reserve the right to change the given data without notice.

Paint should be looked upon as a semi-manufacture. The result is dependent on construction, the condition of the substrate, pre-treatment, temperature, relative air humidity, application etc.
